Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S26	12891	(((strobe flash) near3 (lamp light tube)) flashlamp) and (trigger\$4 firing)	US-PGPUB; USPAT; USOCR	OR	ON	2004/12/24 13:17
S27	2356	S26 and (voltage near3 (detect\$4 sens\$4 measur\$4))	US-PGPUB; USPAT; USOCR	OR	ON	2004/12/23 20:44
S28	79	S27 and (zero near2 crossing near3 (detect\$4 sens\$4 measur\$4))	US-PGPUB; USPAT; USOCR	OR	ON	2004/12/23 20:49
S29	49	S28 and (comparing comparator)	US-PGPUB; USPAT; USOCR	OR	ON	2004/12/23 20:48
S30	1335	S27 and (strob\$4 flashing)	US-PGPUB; USPAT; USOCR	OR	ON	2004/12/23 20:48
S31	55	S30 and (zero near2 crossing near3 (detect\$4 sens\$4 measur\$4))	US-PGPUB; USPAT; USOCR	OR	ON	2004/12/23 20:49
S34	1923	(((strobe flash) near3 (lamp light tube)) flashlamp) and (trigger\$4 firing)	EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/12/24 13:18
S35	867	S34 and (storing charging dis\$1charg\$4)	EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/12/24 13:19
S36	72	S35 and ((voltage current) near5 (detect\$4 sens\$4 measur\$4))	EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/12/24 13:20